
Висовоз DASSOC. MUNI CT ☐ CONTINUATION C MISCELLANEOUS
☐ SUPPLEMENTAL ☐ FOLLOW-UP INCIDENTAL REPORT Paga. a BEAT/SECTOR 4 REF. COMPLAINT NO. S. TIME M 7. DATE THIS REPORT 88-15050 1103 OCCURRED 9. LOCATION (Address of Occurrence) Menotone
[13, SEX ] 14 HOME PHONE 1537 h 18. BUSINESS PHONE 16. CODE PERSON'S RELATIONSHIP TO INCIDENT: V-Victim W-Witness R-Reporting Person P-Parent S-Person Securing Building **D-Person Discovering Crime** A-Person Accepting Document 17. NAME (LF.M)/RACE/SEX 19. ADDRESS/ADDRESS CHECKED 20. PHONE (DAYS) 21. 5 18. 008 22. 23. STATUS GTY. 25. SERIAL NUMBERS OR OWNER APPLIED NO. 26. BRAND, MAKE OR MANUFACTURER 24. ARTICLE NAME 7. MODEL NAME AND 28. MISCELLANEOUS DESCRIPTION MODEL NUMBERS MAR 1 6 1986 and 1537 N. Classtone DEN 31. REVIEWED AND APPROVED DSN 32. INVESTIGATE CASE STATUS Millson 537 ☐ Open ☐ Cleared A Suspended ☐ Unfounde





STATE OF MISSOURI

#### FACSIMILE TRANSMITTAL SHEET

DATE 5-14-92

FAX DUMBER

FROM

CHUCK KROEGER

DNR

FAX DUMBER

FAX DUMBER

HE

SPECIAL INSTRUCTIONS/REMARKS

doubt that it is a regulated amount.


Any Guestions, give me 4 CALL

ANY PROBLEMS WITH TRANSMITTAL, CALL

545-6950

TOTAL NUMBER OF PAGES (INCLUDING TRANSMITTAL SHEET)

2\_



### INDUSTRIAL WASTE INVESTIGATION AND SURVEILLANCE STATUS REPORT

FIRM NAME MONTGOMERY TEXACO TERMINE	26-
ADDRESS 1537 N. GIENSTONE	
PERSONNEL CONTACTED NORRIS MONTGOMERY	POSITION BUNER
	POSITION
	POSITION
ACTION INITIATED BY: Cooses Lymps. Par	BST. CRISWELL
1). 1-30-73- CRISWELL LETTER TO MONTGOMER 2). 2-5-73- MAR ILLUSTRATING PROBLET	y informing A PROBLEM EXISTS.

1537 N. 6/anstone

January 30, 1973

Montgomery Texaco Terminal Service Station 1537 North Glenstone Springfield, Missouri 65803

Dear Sirs:

This office has made a cursory inspection of your property on a number of occasions recently. Our findings indicate that a significant quantity of oil leaves your property to the east into a storm channel immediately tributary to the North Branch of Jordan Creek. Spillage on the lot is usually washed off to the front through openings in a retaining curb. The appearance of the ditch indicates the possibility that more oil enters than from simple lot spillage.

Please be advised that the discharge of oil is strictly prohibited by City, State, and Federal Law. Please contact this office within the next week and advise us of a time convenient with you when we might meet with you to discuss this problem and possible solutions.

If we may be of any assistance or can answer any questions, please do not hesitate to call.

Yours truly,

Charles H. Criswell Chemist and Aquatic Bi logist Industrial Waste Surveillance & Enforcement

CHC:cc

cc: Mr. Steve Decker, Regional Engineer, Missouri Clean Water Commission

March 1, 1979

Mr. Norris Montgomery 1537 A North Glenstone Springfield, Missouri 65803

Dear Mr. Montgomery:

On a recent occasion, surveillance and enforcement personnel from this office investigated a complaint and found that a substance resembling crank case oil had apparently been drained or discharged on the south side of your building.

Let me advise you that if this spillage is due to any activities on your part, this constitutes violations of City, State and Federal Laws. The laws contain severe penalties for the discharge of oil or petroleum products. This office maintains periodic surveillance throughout the corporate limits of the City, and will watch this area closely. If the discharge described is not due to any activity on your part, you can help significantly by reporting any such activities immediately to this office.

If we can be of any help or can answer any question, please do not hesitate to call.

Yours truly,

Gene Pabst Water Pollution Control Inspector Surveillance & Enforcement

GP:pg

cc: John R. Nixon, Regional Administrator, Missouri Dept. of Natural Resources

# OFFICE

# **MEMO**

To:

**WAYNE LATIMER** 

From:

Gene Pabst

Subject:

Grease in the sanitary sewer line - 1600 N. Glenstone.

Date:

October 1, 1997

I inspected the grease interceptors at the following restaurants:

#### 1) **HONG KONG INN - 1645 N. GLENSTONE** (2:45 P.M.)

I talked to the owner (Si) of the Hong Kong Inn and he said that he did not know he had a grease interceptor. It is located outside on the West side of their building. I opened the two lids on the interceptor and it was completely full of grease. The flow of water was "short circuiting" across the top of the grease. I told him that he needed to have it pumped out. He said he would call someone immediately. I then checked their sampling manhole. The manhole was not completed at the time of construction. The manhole needs to have concrete poured for the floor and the invert cut out. I told the owner that he should call the contractor who remodeled the building (Honk Kong Inn has only been at this location less that 6 months) and have him get the plumber to finish the installation of the sampling manhole. I gave the owner my card and told him to have the contractor call me if he has any question. I also told the owner that he should periodically inspect the grease interceptor to get an idea as to how often he needs to have it pumped out.

#### 2) **BUCKINGHAM'S - 1635 N. GLENSTONE** (3:00 A.M.)

I talked to Dustin (the owners were out of town and no manager was in the restaurant at that time) about their grease interceptor. He knew nothing about it. He wanted me to show him where it was located so he would know what I was talking about and he could relay the information to the owners. Their grease interceptor is located outside on the West side of the building. I opened both lids and it appeared to be in good working order (they have only been open for 4 months). Dustin told me that they only use paper plates, do not have an automatic dishwasher, have no deep fryers, have a three vat sink and that they do all of their cooking in the smokers. All the grease from the smokers is captured and placee in the grease dumpster. I looked in their sampling manhole and found no evidence of grease. I gave Dustin my card and told him to have the owners contact me when the return and that I would explain to them about the need to periodically inspect the grease interceptor to know when to have it pumped.

WAYNE LATIMER Page 2 October 2, 1997

#### 3) **PIZZA INN - 1631 N. GLENSTONE** (3:15 P.M.)

I inspected the sampling manhole at the Pizza Inn and found no evidence of grease. They do not have an outside interceptor. I did not go inside to talk the manager because I don't believe they do any cooking at this location.

## 4) **OLD MONTGOMERY TRUCK STOP RESTAURANT - 1537 N. GLENSTONE** (3:20 P.M.)

I inspected their sampling manhole and found no evidence of grease. I talked to the person leasing the building (Edna Hardwick) and she did not know where their grease interceptor was located. I found two interceptors, one under the sink and another one after the automatic dishwasher. I told her that she needs to periodically inspect the interceptors to make sure they are working properly and to see if they need to be cleaned out.

I believe the problem of grease in the City sanitary sewer line is coming from the Hong Kong Inn. I will stop by again in a couple of days to make sure that they have pumped out their interceptor. I will also watch to make sure that their sampling manhole is completed.

cc: Randy Lyman

File



1.000 Springfield

August 15, 1979

Mr. Norris Montgomery 1537 A North Glenstone Springfield, MO 65803

Dear Mr. Montgomery:

Representatives of this office and the Springfield Sanitary Services recently inspected the drainage below the Montgomery Texaco Truck Terminal in Springfield, Missouri. During that inspection, it was noted that there was a considerable amount of petroleum products pooled in the ditch and that it would undoubtedly be discharged to waters of the state during a rain. This constitutes a violation of the Missouri Clean Water Law, Section 204.051, Part I which states that it is unlawful for a person to permit to be placed, any water contaminant in a location where it is reasonably certain to cause pollution. A discharge of oil would constitute a violation of Section 204.051, Part 3 which states that it is unlawful to discharge any water contaminants into any waters of the state which exceed effluent regulations. The effluent regulations (10 CSR 20-7.020) state that there shall be no visible discharge of oil and grease.

We recommend that you take whatever steps that are necessary to eliminate the oil in the ditch and prevent discharges of oil from your lot. If more careful handling of petroleum products proves ineffective, it may be necessary to install a trap with baffling to catch the oil before it discharges.

Representatives of this agency will reinspect the drainage in the near future. Improvements should be evident at that time. If we can be of any assistance to you, please advise.

Yours truly,

Charles L. Kroeger

Environmental Specialist II Springfield Regional Office Department of Natural Resources

Charles Logorge

CLK/jo

cc: Mr. Steve Short - City of Springfield, Sanitary Services